## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200308733-1
IN RE APPLICATION OF: U.S. Patent No.: 7,200,604
USPTO CONFIRMATION CODE: 9657
APPLICATION NO.: 10/780,235
FILED: Feb. 17, 2004
EXAMINER: Cheryl Lewis
GROUP ART UNIT: 2167
FOR: DATA DE-DUPLICATION

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION
HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS
Sir:

The following is a request for a certificate of correction in Serial Number 10/780,235, now Patent Number 7,200,604.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a furthe fee is required, please charge the amount to Deposit Account No. 082025.
All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.
The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 4, line 38, after "log of" delete ""in"" and insert - - "m" - -, therefor. (Amendment to specification filed on Nov. 13, 2006, page 2, line 7)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

3/27/2009

DATE

/Lloyd E. Dakin, Jr., Reg. # 38,423/

Name: Lloyd E Dakin Registration No.: 38423

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration P.O. Box 272400 Fort Collins, Colorado 80527-2400

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO

: 7,200,604

**APPLICATION NO. : 10/780,235** 

**ISSUE DATE** 

: Apr. 03, 2007

INVENTOR(S)

: George Henry Forman, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 4, line 38, after "log of" delete ""in" and insert - - "m" - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.